

# TERMITE SERVICE REPORT

9725 C6

## Tidewater Termite & Repair, Inc.

133 Tilden Avenue • Suite C  
Chesapeake, VA 23320  
757-312-8081

Invoice 118209

Customer Name <b>Ryland &amp; Alicia Sherman</b>	Date <b>9/5/2025</b>	Account # <b>10842</b>
Service Address <b>4210 Cornland Road</b>	<b>9-11 am</b>	Contract Period: <b>August 2025 - August 2026</b>
<b>Chesapeake, VA 23322</b>	<b>Meet owner</b>	Renewal Amount <b>\$108.00</b>
Phone # <b>845-264-4854 Mrs</b>	Work Phone # <b>Home only</b>	

### TYPE OF CONSTRUCTION - FOUNDATION

- Log Home     
 Monolithic Slab     
 Basement     
 Supported Slab     
 Piers Only - Open Foundation  
 Combination     
 Crawl     
 Floating Slab     
 Mobile Home

### INSPECTOR FINDINGS

- A.  No active evidence of termites found      B.  Live activity indicated

If "B" is checked above, retreatment will be recommended.

Retreatment is scheduled for \_\_\_\_\_ between \_\_\_\_\_ and \_\_\_\_\_ am/pm

Please contact our office to schedule a retreatment date.

### FACTORS WHICH MAY LEAD TO INFESTATION

- Inadequate ventilation in crawl space     
 Wood mulch     
 Wood-earth contact  
 High moisture condition/water leakage     
 Faulty gutters/No splashguards     
 Tree branches touching structure  
 Siding less than 6" from grade     
 Wood debris in crawl space     
 Landscape timbers  
 Firewood against structure     
 Poor drainage condition     
 A/C condensation

Comments: **NO TREATMENT NEEDED, INACTIVE FUNGUS AND MOISTURE DAMAGE IN CRAWL AREA**

If it is very important that you remedy the conducive conditions noted above. If you fail to do so, it is probable that your structure will experience future termite activity and damage and retreatment by Tidewater Termite & Repair, Inc. may not solve the termite problem. Please notify us in writing when you have corrected these conducive conditions.

### PESTS OR EVIDENCE FOUND

- Carpenter Bees     
 Carpenter Ants     
 Wood Boring Beetles  
 Ants     
 Spiders     
 Roaches  
 Rodents     
 Other \_\_\_\_\_

Additional treatment recommended:  Yes       No

This report is limited to a visual inspection of the exposed structure. There may be hidden infestations and/or damage that are not evident from a visual inspection. The purpose of the inspection report is to document areas of concern from the interior and exterior inspection. Specifically: (1) Whether or not live activity is indicated; (2) Visible factors which may lead to infestation.

CUSTOMER	YES	NO
Have you made any additions or modifications around the structure since treated by Tidewater Termite & Repair, Inc.?	<input type="checkbox"/>	<input type="checkbox"/>
If Yes, Location: _____		

(The work has been performed and explained to my satisfaction.)

*Ryland J. Sherman*  
Customer's Signature

*WKE [Signature]*  
Inspector's Signature (if applicable)